

IMPROVE YOUR

Here's how you can help your supply support give you better, faster service.

1. Use the preprinted-prepunched DA Form 2765's support gives you. They have the latest info on an item, and they save you (and support) time and work.

ALL THE INFO'S HERE, BUT USE A PREPRINTED 2765 ANYWAY!



2. Use correct FSN's and nomenclature on your DA Form 2765's. Be accurate in all the fill on your requests. Read the request over carefully before you shoot it over to support. Remember, your requests are mostly handled by computers ... and the machines will spit out any requests that have wrong or incomplete info.

INCOMPLETE INFO! THIS IS A RECORDING.



YOU CAN MAKE

3. Learn to read the codes on the supply status cards (card columns 65-66) support sends you. The codes give you important scoop on your request. To translate the codes see App II-17, AR 725-50. Follow through on the code's instructions soonest.



4. Check for new or corrected FSN, nomenclature, unit of issue, etc., info on your supply status cards, and on the copies of your request which support sends you. Add the new info to your supply records right away. Toss out any old preprints that have outdated info.



5. Follow the rules in AR 710-7 carefully when requesting non-FSN'd, non-supply items.



6. Use your PD (Priority Designator) and NORS (Not Operationally Ready) codes right. See Chap 2 and App Π -15 in AR 725-50 for those codes.

SUPPLY

7. Play fair with your DX supply types. Return your unserviceable-repairable items to them soonest. They can fix 'em fast, but DX must have your cast-off's to keep its bins filled.



8. Send follow-up requests on due-in's as called for by AR 710-2, para 2-25 and by your local SOP.



9. Cancel items no longer needed. Stop the supply action on your request soonest. This, too, saves unnecessary sweat all around.



10. Talk to your support outfit when you have supply problems. They're in business to support your needs... and they've got what it takes to do it ... the latest supply info, the latest supply publications, and loads of experience in the supply field, too. So stop frettin' and get friendly with 'em. You'll find that a good supply system depends a lot on what you do. Give it a try right now.



routised by the operation of the Arthor the Information of organization maintenance and supply personnel Ditribution is made through normal pub cation channels Within limits of availability older issues may be obtain direct from U.S. Army Maintenan Board, Attin PS. Magazine Fort Kno Kentucky, 40121.

THE PREVENTIVE MAINTENANCE MONTHLY
ISSUE No. 230 1972 Series
January
IN THIS ISSUE

FIREPOWER 2-9

| Bayonet-Knife & | | Tank Escape Hatch | 6 |
|-----------------|-----|---------------------|---|
| Scabbard | 2-3 | Ballistic Computers | 7 |
| M12 Rifle Rack | 4 | Elbow Tips | 8 |
| M67 RR | 5 | M36 Periscope | 9 |
| M40-Series RR | 5 | M551 Transmission | 9 |



GROUND MOBILITY 10-17

| Multifuel Engines 10 | -11 | M11 Trailer | 14 |
|----------------------|-----|---------------|----|
| Multifuel Dipstick | 12 | M172A1 Semi | 15 |
| M715 13, | 17 | M816 Wrecker | 16 |
| XM747 Transporter | 14 | MG Ring Mount | 17 |
| | | | |



COMBAT SUPPORT, SUPPLY

| D7E Tractor | 18-28 | New Publications 64 |
|--------------|-------|-----------------------|
| UND/PD Codes | 60-63 | Supply 3, 4, 5, 6, 8, |
| | | 11, 14, 15, 49, 52, |
| | | EC and E7 |



COMMUNICATIONS 37-49

| BA-4386, | | AN/PPS-5A | 41 | |
|------------------|----|-----------------|-------|--|
| -386/PRC-25 | 37 | AN/PRS-4 | 41 | |
| R1-505 | 38 | Starlight Scope | 42-43 | |
| AN/PRC-25 | 38 | AN/URC-68 | 43 | |
| AN/VRC-12 | 39 | AN/MRC-69 | 44-47 | |
| C-2298/VRC | 39 | C-3835/ARC-54 | 48 | |
| AN/GRC-103, -106 | 40 | R-844A/ARN-58 | 49 | |
| APH-5 | | 49 | | |



AIR MORILITY SO SO

| MI | I MODIL | 111 20.23 | | |
|-------------|------------|-------------------|----|--|
| 0H-13 | 50-51 | Hydraulic Systems | 57 | |
| UH-1 | 52, 53, 59 | Filter Elements | 57 | |
| CH-47 | 52, 56 | Mil Spec | 58 | |
| Inspections | 54-55 | U-21, U-8 | 58 | |
| AH-1G | 56 | FOD Corner | 59 | |
| | | | | |



Use of funds for printing of this publication has been approved by Headquarters, Department of the Army, 22 January 1971. DISTRIBUTION: In accordance with requirements submitted on DA Form 12-4.


PS wants your ideas and contributions. and is glad to answer your questions. Name and address are kept in confidence. Just write to: MSG Half-Mast, PS Magazine, Port Knoz, Ky.



Chances are you'll have either the M6 or M7 but these are the points to check on any bayonet-knife:

- Latches must snap back under spring tension when depressed and lock the bayonet-knife securely to weapon.
- 2. No rust or corrosion on metal surfaces.
- 3. Cutting edges of blade not nicked or turned. (If the blade tip is broken the weapon is unserviceable.)
- 4. Weapon fails inspection if misalinement between blade and handle is over 3/16 inch.
- 5. Slight looseness of guard is allowed. (Don't try to cure this by welding the guard to the blade—it'll take the temper out of the blade and weaken it.)

6. If grips are cracked or broken the knife won't pass inspection. (Turn it in for repair. Your armorer can get the parts.) Make sure your bayonet-knife and rifle mate up:



M8A1 SCABBARD

No matter what bayonet-knife you have, from the M4 through the M7, it'll be issued with an M8A1 scabbard. Check-points for both the M8A1 and the M1917

1. Scabbard must grip bayonet-knife so tightly that it will not fall out even when upside down.

2. All metal parts dark in color.

3. No bare spots on painted surfaces. If finish on metal parts is worn or shiny in spots, your armorer can dull up those spots with flat, black, lacquer, FSN 8010-582-5382 for the 16-oz presurized can.

If local SOP requires ID markings on scabbard, paint 'em, on the metal tab, not on the scabbard body. This is so the ID marks can be painted out when the scabbard is ressued.

RESTRAINING LACE—Serviceable.
If not, get a new one—FSN 1005-300-5378.

stitching, rivets and

hanger secure.

MAINTENANCE AND REPAIR

TM 9-1005-237-15P (Jun 67) has the maintenance and repair parts list for bayonet knives M4, M5, M5A1, M6 and M7, and the M8A1 scabbard. TM 9-1005-303-14 (Jul 68) covers the US 1917 bayonet and scabbard.



Dear Half-Mast,

We're swapping our M14's for M16's. Is there a standard arms storage rack for the M16's?

Also, can the adapter used to accommodate carbines in the M11 arms storage rack—TB 9-1095-200-30/1—be used for M16's?

CPT H. T. I.

Dear Captain H. T. I.,

It's your lucky day, Sir. A new M16/M16A1 rifle storage rack—M12—has just been added to the system under FSN 1095-407-0674 and will be available in the near future.

If you want to adapt the M11 rack for your M16 rifles, you can get drawings, a list of tools and equipment and instructions from:

> Commanding General U.S. Army Weapons Command ATTN AMSWE-MAS Rock Island, 11, 61201

They also have poop for adapting M1 and M3 racks to accommodate M16 rifles equipped with the M203 grenade launcher.

HERE'S THE EASY WAY TO GET IT ALL TOGETHER.



IN M12 RIFLE RACK

How much hammake before it's all hamme

M67

I DON'T LIKE THE LOOKS OF YOUR HAMMER!

CHECK HAMMER FOR WELT

How much hammering can a hammer take before it's all hammered out?

The firing hammer on your M67 recoilless rifle takes a hammering from the sear, whenever you pull the trigger.

In time this can raise a half-moon shaped "welt" in the metal of the hammer and keep the hammer bushing from fitting the way it should.

When this happens, there's nothing to do but get a new firing hammer.

. So check your firing hammer from time to time and tell your armorer if it looks too "moony".

MADE FOR EACH OTHER

ONE SHOT AND I'M SHOT!

You M40-series recoilless riflemen want to fire the maxi-number of rounds through those M106-MM rifles? Sure you do!

Then be sure the vent bushing's serial number matches its identical twin number on the breechblock.



You're dealing with a matched set—vent assembly, FSN 1015-340-3426. Your job is to keep matched sets on the same weapon ... and replace both items even if only one of 'em is damaged.

When you replace the vent assembly (breechblock plus vent bushing) make with the paperwork. Update DA Form 2408-10 (Equipment Component Register) to show the new vent assembly serial number. Also enter this information in the remarks column of DA Form 2408-4.



Using a piece of wire or rope to hold the driver's escape hatch shut when the rubber torsion spring gets worn out?

That's what some guys are doing, and it's strictly a No Good deal. Why?

Because when the driver wants out through the escape hatch in a hurry (like maybe the tank's on fire) he's got no time to be untying a lot of wire or rope.



So, check out the condition of the hatch closing spring. If the hatch handle won't snap back at once to a completely locked (closed) position, then the spring is no good. It's got to be replaced.


Support maintenance repairs or replaces this spring according to the last paragraph on page 2-449 of your TM 9-2350-215-20 (Feb 65) for the M60/M60A1 tanks or page 2-409 of your TM 9-2350-224-20 (Jan 66) for the M48A3.

Your DS orders it like so-

| TANK | SPRING ASSEMBLY | | |
|---------------------------------------|-----------------------------------|--|--|
| M48A3 | FSN 2540-105-6131 (PN 8674454) | | |
| M60 and early M60A1 ROUND HATCH | FSN 2590-948-1496 (PN 8335562) | | |

GET
YOUR
WORK ORPER
TO YOUR DS...
AND FORGET
THE HANDYMAN
WIRE OR ROPE
REPAIR,





Both the M13A1D and the M13A2 are interchangeable and you might find either one in your M60 or M60A1 tank. (Except it takes an added part—Cap, actuator, superelevation, FSN 2590-178-0205—to adapt either computer for use with the M60A1 tank.)

The design differences—handle and range scale illumination—don't shake anybody up, but the zero check point does.

So do it like this, by the numbers.









2. Line up the index line on the input shaft with the input cover index line.



4. When you get the index lines in register, connect the range input shaft and coupling.



THE LARGE NUT ...

SMALL NUT

I'VE GOT

ONE TOO

MANY

ELBOWS!

On all M60/M60A1 and M48A3 tanks, M728 CEV's and AVBL's, there are 4 elbows that join the transmission oil lines to the transmission oil cooler.

These elbows, FSN 2815-678-4247, (the supply manuals call 'em tubes) are getting busted up by the hundreds because hardly anybody knows how to tighten 'em right if they start to leak.

The thing not to do is to bang on these nuts with a hammer and chisel.

The right way is to tighten up the big nut and then the smaller nut—which acts as a jam nut to seat the tube. They are tightened in production to 58-68 lb-ft torque. If a leak occurs below the large nut, replace gasket, FSN 5330-269-2845. A leak around the small nut could mean the tube seat is distorted. TM 9-2350-215-20 (Feb 65) has the dope on pg 2-239.

THIS

IS NOT

For the larger nut use an open end wrench (1%-in) from the No. 2 Common tool set. For the smaller nut use an open end wrench (1½-in) from your No. 2 Supplemental tool set.

NOTE: If you have to get at the nuts on the rear elbow, you may find it easier to take the forward (outboard) elbow off first.

To tighten the rear elbows when the shroud is still on the vehicle you have to go through the side access opening and the shroud access plate opening. You may save time if you take the shroud off the vehicle.

When you have to couple the oil line to the elbow, go easy on the coupler nut. Tighten until you get first sign of resistance on the wrench ... then give it just a quarter turn more. That way the nut will be secure but you can still get it off easy if you need to.

Run the engine before installing the shrouds to make sure there are no leaks.



There's a 47-cent item protecting umpteen dollars worth of equipment on the M60A1 tanks, the M728 CEV's and some modified M60's.

It's the spring on the cover of the M36 commander's periscope.

Once it's sprung you can't shut the cover tight.

This means water in the optics or soaked sighting and fire control instruments or water in the hull.

Don't get into any mess.

Keep the cover shut when you don't need it open.

Hands off, too—flipping it back flat or straight up will stretch the spring out of shape and maybe bust a bushing.

Open it only with the shield handle and only to view through the periscope—then, only to 90 degrees.

If you find a spring that's gone haywire, don't fool with it. Have your direct support replace it fast.





M551 TRANSMISSION TROUBLES

Too many transmissions on M551 Sheridan vehicles are getting busted beyond repair when drivers get confused about using the water steer lever.

It's really pretty simple, like so ...

Make sure the steer lever is in the "Land" position before you start the engine.



B. Shift back to "Land" position the last thing before you leave the water after you've been swimming the vehicle.



This may not look like \$8,500 worth of knowledge but it is—that's what a replacement transmission costs.

See Table 2-4, Amphibious Operation, on pgs 2-15 to 2-20 in your TM 9-2350-230-12 (Jun 66) for all the details.



GOT A
MINUTE?
I'D LIKE TO
SHOW YOU
HOW TO PUT
IT ALL
TOGETHER!





You don't have to be as sharp as a watchmaker to put an oil filter back together like the twin filters on those multifuel engines.

You just have to be careful!


This goes for all 2½-ton multifuel trucks (LDS 427-2 or LD 465-1 engine), those 5-tonners with the LDS 465-1 or LDS 465-1A engine and the new 8x8 5-ton jobs (M656 etc.) with the LDS 465-2 engine.

Yep, some guys are putting the filters back together wrong.

Then the filters leak ... or the parts inside get busted up ... or the filters just don't filter.

So let's step back from the woods for a minute where we can see the trees.

Here're the 8 parts you've got to put together when you're changing the oil filter element—and this's the order for putting 'em together:



A new filter element and gaskets come in Parts Kit, Oil Filter, FSN 2940-884-4801—check your truck's TM -20P. You may get more parts than you need in this kit—an odd gasket and a couple of cotter pins—so just toss out everything except the element, the housing seal (gasket) and the little gasket that goes on top of the housing.

MULTIFUEL ENGINE OIL CHECK

HERE'S SOMETHING TO WRITE HOME ABOUT!

Dear Virginia:

Yes, Virginia—and all you multifuel truck jockeys—the-10 operator's TM's will be coming out with the straight poop on checking the crankcase oil level.

Fact is, it's already in Ch 7 (May 71), TM 9-2320-209-10—check page 43.

You should've got the word from your own local command back when they got it in TB 750-981-3 (Jul 69).

It comes down to this:

It's normal for your dipstick to read a little over the FULL mark—about 1½ inches—when your engine has been shut down for several hours. That's for a cold engine.

But when you check the oil level one minute after shutdown—when the engine's still hot—it should not be above the FULL mark. Any place between ADD and FULL is safe.

Natch, cold or hot, you add oil if the level's below ADD!

Not enough!

Anywhere between ADD and 1/2 inches
above FULL is safe.

ADD 4 2 FULL CHECK OIL

Hot Engine

Anywhere between ADD

and FULL is safe.

Remember, now, that you don't screw the dipstick down when you're checking the oil level. Just be sure you screw it back down after you're all done with your oil check.

This's 'bout the story you'll be seeing in TM 9-2320-211-10 and TM 9-2320-230-10 for those multifuel engines—and in the lubrication orders for those trucks, too.


P.S. If you see Ernie S, tell him I need my tennie racket fove,



Trying to figure out why oil's leaking around the rocker arm cover on your M715-series 11/4-ton truck?


Maybe you've got the gasket on backwards. That gasket's shaped inside to fit the lip of the rocker arm cover.





Take a look. You don't have to take it oft. If there's no groove running along the outside of the gasket, you've got it on wrong. You'll have to take the cover off and put it on right.

COME AND GET 'EM!



195, 198, 199, 200, 202, 203, 204, 205, 206, 207, 209, 211, 212, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 226, 227, 228 and 229.

If you've got any extra copies around your shop, send 'em to the PS office. Other guys can get 'em that way.

A STATE OF THE STA



HEED

THIS NEW

WHEEL-BEARING

NUT TORQUE

WORD!

Make that 200 lb-ft torque, instead of 50, when you're tightening the wheel-bearing nut on your XM747 heavy equipment transporter.

You need this to make sure the bearings are seated good. Otherwise, you'll have trouble with binding and heating up in the hub-drum. And the bottom brake lining will wear out quick, too.

That 50 lb-ft torque in para 3-35i(3), TM 9-2330-294-14 (Apr 70), is not near enough!

But make sure you stick to the rest of that poop in para 3-35i(3), and (4)— rotating the wheel in both directions while tightening the adjusting nut, then backing off the nut 4-% turn... and so on.



Need a taillight/turn signal lamp for your 21/2-ton M11 trailer, FSN 2330-697-8102?

Depending on the socket- you have, one of these will do it:

Lamp, incandescent,
24-volt, G.E. (No.
1275. Be sure to
give the part number. Order by exception-data and
specify "No substi
tute accepted."
(RIC is \$96)

Lamp, incandescent, Part No. 1662, FSN 6240-877-3405. No need to request hand-process here.



The 2 bulbs aren't interchangeable—the locking pins on the No.1275 are opposite each other, while the 1662 has one higher than the other.



Dear Half-Mast.

What's the scoop on wheel-mounting hardware for our M172A1 25-ton semitrailers?

What the TM shows and what we've got on the trailers don't stack up.


SP5 H. M. S.

Dear Specialist H. M. S.,

Until the right poop shows up in a change to TM 9-2330-211-14 (Oct 69), you'd better make a note on this someplace:

Your M172A1 got new wheel nuts and studs under MWO 9-2330-211-30/3 (Jun 66). Or, if it came out of the factory after that time, the new hardware was already on it.

Now, from the inside-out, here's the whole setup:





That crane on your new M816 5-ton wrecker can get shafted in the drive shaft if you slip up on seal case lube.

Low lube level in the bevel gear seal case or power divider seal case whips you. There's just no way for those upper and lower shaft bearings to get oil except from those seal cases.





Just ½ inch too little lube lets the bearings cook. A torn boot brings the same payoff. Then even if you do bring the level up, you're just feeding a leak.

Three timely tricks fortunately will fend off such evil fortune, like so-

1. Take for gospel what 10 9-2320-260-12 says about keeping seal case lube up to the threads on the side fill plug ... in both cases.

2. Eyeball and feel that boot, and finger the shaft for any stray lube dripping down

3. Every time you move out, be sure that lever behind your hand brake—your power divider lever—is locked out of gear. Rolling along the road with that lever forward will get you barbecued bearings, lube level or no lube level. The reason is, at highway speeds, it'll turn the shaft about 450 RPM faster'n it's s'posed to go. Care there can save your





Ord 8 SNL A-55, Section 50 w/Ch 1 (Oct 66), for support-level repair parts. (When you're issued a new mount, make sure your support gets the packing list—they'll need it for some of the parts that're not listed in their supply manual.)

SAVE COIL EARS

I CAN'T HEAR YA, I'VE GOT A WASHER IN MY EAR,

Switch the washer on ignition coils for M715 family and M151 series trucks.

Take the flat hold-down washer from under the screw head stud and put it under the ear. Your star washer will keep the screw tight, and the "cushion" of the other washer will help stop ear crack-off.





BE YOUR OWN INSPECTOR ...

DO YOUR OWN PM THING WITH THE DIE TRACTOR.
SET UP YOUR INSPECTION LIKE YOU MEAN BUSINESS ... YOUR BUSINESS!


The serious faults are indicated by **BOLD ORANGE TYPE**— serious enough to deadline the tractor: Get 'em fixed-but quick!


Where do you start? Armed with your DA Form 2404, walk up to the front of your tractor, natural-like and go to it.

If you have any questions, shoot 'em to your unit mechanic. He'll be glad to give you straight answers. He's the fixer.

BASIC ISSUE ITEMS—All on hand? Listing is in TM 5-2410-214-12 (Jun 68).


PUBLICATIONS-Missing, torn, unreadable, not up-to-date. Check in DA Pamphlet 310-4.





MOUNTING PINS—Worn, loose, Safety pin missing.

SCARIFIER-Broken, cracked. Hinge pin missing, stuck, bent.



CUTTING EDGE-Worn, chewed up, bolts missing or loose.

END BITS—Worn, chewed up, bolts missing, or loose.

TILT CYLINDER—Leaks: bolts loose, Piston rod badly scored, dry.

TREEDOZER (ROME PLOW)

CLEARING BLADE POINT—Dull. (Keep a well-shaped fillet—too sharp a corner will promote cracks.)


> WEB- Dull, out of shape. curled.


CUTTING EDGE-Dull, cracked, curled. (Check with template, see page 23, TM 5-3830-236-12 (Oct 69).

HYDRAULIC LINES-Kinked, badly chafed, leaks, fittings loose.



PUSH ARM— Broken, cracked. mountings loose.





THIS IS GREAT, WHEN IT'S BROKE DOWN INTO SECTIONS.

REAR

REAR FLOOD LIGHTS-Glass broken. clouded. Wires broken, fraved. Mounting loose. Burned out.

SCRAPER MANIFOLD—Lines worn, loose. Flange bolts missing ... leaks.

FLIFI TANK—Crushed, mounting bolts loose. Leaking. Rusty. Water in tank. Cap missing; loose (Does it seat right?). Strainer broken, missing.

WINCH—Damaged housing, cracked, mounting loose. Cables kinked, broken strands, rusty, not oiled. Coupling damaged. Oil level low (Check every 50 hours).

RIPPER—Shanks out of adjustment) job layout determines placement). Hydraulic Hoses: Breaks, worn, cracks, kinks. Hydraulic cylinders: Bent, piston rod dry, badly scored, leaks. Frame: Cracked, bent. Pins: Wear, missing, peening. Mounting Bracket: Stud nuts missing, loose (stud nuts must be torqued to 1500 ft-lbs).

TOW HITCH-Pin missing, cracked, broken.

RIGHT SIDE

TOOL BOX-Lid catches broken. Rusty, broken, stuffed with oily rags, junked up.

DON'T SLACK OFF NOW, BE SURE TO CHECK ALL THE ITEMS YOU CHECKED ON THE LEFT SIDE

DOZER HYDRAULIC TANK—Filler screen broken, gasket missing, deteriorated; cap missing, oil low. Filter cover assembly: Cracked, screws, bolts missing,

EXHAUST-Loose. Not covered when tractor is stored outdoors. Flutter valve sticks. (Water down the exhaust pipe may cause hydrostatic lock and engine damage.)

TILT BRACE—Bent, loose.






REAR CRANKCASE GUARD—Cracks, breaks, bolts missing. Access cover broken, missing, loose, dirt or foliage packed.





TRACK FRAMES—Cracked, loose or missing bolts; broken parts; mud packed.

FRONT CRANKCASE GUARD—Cracks, breaks, bolts missing. Pull hook broken, mounting loose. Dirt or foliage packed.

missing. Dirt or foliage packed.









OPERATING PRECAUTIONS

Never operate electric starter more than 30 seconds at a time. Allow 2 minutes for cooling before using starter again.

Safety lock must be ON when tractor is parked and engine's running.



Don't switch on HEAT-START when engine is warm and running.



Let lube get to the turbocharger.



Keep your treedozer blade close to the ground when you work.

Don't use tractor in land clearing operation unless you've got the engine and cab guard protection kits mounted.

Take a break now and then to check over your tractor.




Shutting down, let engine idle 3-5 minutes to slow down turbocharger to avoid bearing burn-out.

Never turn OFF disconnect switch while engine is running.

Keep TM 5-2410-214-12 (Jun 68) handy.

Get your own copy of TB 385-5 (Mar Don't rev up too fast when starting. 70), the safety manual on operating and maintaining the crawler tractor.



LO 5-2410-214-12-2 (Nov 70) TM 5-2410-214-12 (Jun 68) and Ch I (Oct 70)

TM 5-2400-200-ESC (May 69)

TB 385-5 (Mar 70)—Operation and Safety TM 5-3830-236-12 (Oct 69)-Treedozer













So you're receiving and passing the word with your AN/PRC-25 radio set.


Good enough. But ask your repairman to find out if your RT-505/PRC-25 receiver-transmitter has a "safe" module A3 with the words CRI MOD ADDED on its cover.



If the radio has such a module, no sweat; if the words are not there, keep your set at least 25 feet away from the more powerful radio sets, AN/VRC-12 and AN/VRC-43 through -49.

High power RF output from the more powerful sets damages the receiver circuitry of the RT-505.

This goes for other configurations where the RT-505 is used, like the AN/VRC-53 or AN/GRC-125.



FLUSH TO

ANTENNA

MOUNT

You wouldn't dream of operating your AN/PRC-25 or -77 radio set without an antenna, right?

Then, you wanta be sure you're not operating your set with its antenna but minus a good working connection.

When you screw your whip antenna into the antenna mount, continue screwing the antenna until it is flush with the top of the mount.

As a hedge against vibration wobbles, tighten the antenna into the mount every now and then. Put a sliver of rubber, from a rubber band or eraser, on the threads before screwing it into its receptacle.

Use a flashlight, benchlight, or what-have-you for an occasional examination of the inside of the antenna mount for dirt or other obstructions. Clean it out.



Certain Joes are using the modules of their AN/VRC-12 series radio to make like Michelangelo with a chunk of marble.

These commo types chisel the words "BAD" or "NOT GOOD" into their radio's defective modules before shipping them to support for repair. True, this is a method of separating the bad modules from the good ones but look fellas:


The covers of the modules must be replaced when they're deeply scratched. This causes unnecessary delay and expense.

All identifying marks should be done with a grease pencil or some other nondestructive marking device.



Lost retaining rings on the audio connectors of your C-2298/VRC intercommunication control unit can goof up your auxiliary communications.

Use a spanner wrench to tighten the retaining rings on the J802 and J803 audio connectors.



Why? If you're short the rings, you could find yourself futilely trying to tighten the audio connector to the control-box connector.

Without the rings as stabilizers, the audio connectors simply push back in their sockets and you get no connection.

NO TRAISUTER SWITCH

You say the transmitter fixed head on your AN/GRC-103 radio set has been replaced ... and now you can't get power to the transmitter.

Here's a clue to one problem that could cause it: Full scale deflection of the transmitter front panel meter ... caused by the no-power load.

The bad guy: Pin Al of the
J7 jack can't make contact with the
J6 connector . . . which means 630 volts can't
make it to your Type 7211 tubes.

Add, or have your support add, enough shims to the J7 so it'll seat right in the J6.

To prevent the problem, transmitter heads, where possible, should stay with the same radio set. Don't shift 'em around. When you have to shift 'em, doublecheck the connector to be sure it makes contact.


QQQQQ

AN/GRC-106 DO A GOOD TURN

Lotsa Joes know that an extra-hard turn can snap that long-handled PRIM PWR switch on the AM-3349/GRC-106() amplifier.

But certain Joes still don't know that the same kind of turn can fracture the fiberglass arm in amplifiers that have the short-handled switch.

So, remember: Do a good turn.






Has the RT-692 azimuth counter of your AN/PPS-5A radar set got in a jam lately?

If so, get it replaced, because chances are good that your azimuth readings on all targets are wrong.

Like, if the counter jams ... and moves
on ... the counter clutch slips. And you've got loss of azimuth alinement. Which means your set has to be realined and the counter replaced.

So—check azimuth coverage at the control indicator at least twice during a mission and at the end of the mission.

To check, you've got to know your sector coverage limits. The target azimuth should be within these limits ... and the azimuth position on your B scope should agree with your azimuth counter reading of the target.



CHECK

AZIMUTH COUNTER

You might also check the azimuth reading on your receiver-transmitter with that on the CI. In any case, loss of azimuth alinement is a problem for your support people to handle.

CARE FOR THE CASE

When you're movin' your cased AN/ PRS-4 mine detector set, keep that case away from sharp corners and bulges.

It's a good metal case—it shields the detector from blows and woes—but it can be damaged.



And be extra careful with those 6 latches. If they're bent, broken or lost, the set's left open to damage. You have to replace the latches by cannibalization.



If your starlight scope goes blind, here's how you can make it see again.


First, check the battery. Replacement's simple.



If the battery's all right, have support take a look at the image tube oscillator. This oscillator can fail, and a quick DSU check could slash lotsa hours off its shoptime.



Incidentally, the BB-429/U battery in the AN/PAS-4A night sight no longer is shipped in the sight's carrying and shipping case.



The word's in TB 750-911-1 (Nov 70), page 19, that there's leakage of potassium hydroxide to the PAS-4A even though the case cap is supposed to be leak-proof.

To cut damage, leave the BB-429 out of its case while it's on the move, and keep it upright as much as you can. In the regular carrying case, the battery rides horizontally.

You'll find shipping and maintenance instructions for the BB-429 in TM 11-6140-203-15-3 (Dec 69), Non-Aircraft Nickel-Cadmium Batteries.

A mismounted AN/PVS-1 or -2 starlight scope adapter mounting assembly can shift on its weapon and throw you off when you crave precision.



The bracket must be flat against the top of the rifle receiver, and all the way



NIGHT SIGHT ...

IF YOUR BATTERY'S ALL RIGHT. LOOK YOUR OSCILLATOR TUBE OVER

WHO ARE YOU ?

MOTHER NATURE! N' IF YOU GUYS WANTA SEE AT NIGHT, I'LL FIX IT. I'LL TURN YA ALL INTO OWLS!

Keep the cover on. Also the scope should be in its carrying case any time it's being transported or stored.



Keep the cap on the objective lens when you're carrying your scope by the lever first. Otherwise, you strip the knob.

Don't let sunlight get to the scope lens. sling, for protection against dust and dirt and unwanted light.




When you're ready to turn the focusing knob on the PVS-1, release the locking


PRESERVE THE POWER

To prevent battery conk-out in your AN/URC-68 survival radio, do this:

Place tape over the volume-control knob to head off accidental power turn-on. The knob doesn't lock itself into the OFF position.

Set the MODE switch in the BCN position so that an audible tone will alert you





MORE

moving or replacing 'em, you can damage 7 telephone terminal). You could yank the tuning-head pins, do in the plug, that cord right outta the TS-760 recepcrunch the guide-pins, and catch other tacle, and break the receptacle or botch damage.



WATCH THAT TWIST -In hooking up the power cable leading from the PU-286/G generator to the S-178() shelter, you could give it a crooked twist and strip the threads. Screw that cable on ... using the light touch. If you do accidentally strip the threads, don't try to fix it. It's a support job. Let 'em have it.



The stripped threads can be dangerous. For example, if the stripped end drops from the "power in" receptacle, you've got a live cable on the ground—a sorry situation that could short out a cable and create some danger for you and your buddies.

The TS-760 test plug can come up with a broken cord if it's left plugged in when it's not being used. This could happen if you accidentally knock into it, or catch it on something.

Remember, no yanking on that 3-ft


they're manhandled. F'rinstance, in re- test cord on the TS-760 (on the AN/TCCthe cord wiring.



HOLD THE PROTECTOR -When you remove the test cord, finger-hold the plastic protector instead of the unprotected cord.

When the receiver plug leading from the TT-4() teletypewriter set is not pluged into the TH-22 telegraph terminal set (in the SB-675 patching panel), you stand a good chance of burning out the O-11 transistor if the power is on very long.

The TA-182/U signal telegraph-telephone convertors will last longer if you crank up your equipment 3 times or so per week, and run it about an hour each time. This'll help get rid of the condensation inside the 3 relays. Moisture can cause sticking-and sticking relays can cause repairs.




You can strip the threads in the CHAN-NEL MODEM receptacle when you attach the connector cables. All it takes is a long hard twist on the cable.

The J108 receptacle on the R-417 receiver can be crunched by a P5 connector that's not lined up right. If the male P5 does break the end of the female J108, replace the entire J108 on the AM-1179 tuning head.


PUSHING OFF? - Any time you pack your gear for a trip, make sure you push in the vibration mount lever on the T-302 transmitter. That'll keep the transmitter from dancing around loose on its shocks and doing itself dirt.



Store the H-90/U handset in the CY-1342 accessory case for safekeeping. If you leave it hanging in its cradle on the R-417 receiver, it can be busted while you're moving.



Travel moves can goof up the handset on the AM-707 amplifier-pilot regulator, too. You wanta store this handset in the brackets inside the bin of the RT-280 receiver-transmitter where it can't bounce around and whack itself against the floor or other components of the AN/TCC-7 telephone terminal.









A CHANGE OF SCREWS

YEEP YER COMIN', JOE!

You'll find 1/4-in screws (FSN 5305-770-


You'll find ¼-in screws (FSN 5305-770-2533) lots better for mounting the bottom coverplate to the C-3835/ARC-54 unit control—the reason being that the ½-in screws can play havoc with frequency selection.



It works like this: When the ten ½-inchers are tightened—not wisely but too well—the screw located directly under the frequency selector disk can bind the disk and knock out frequency changes.

The shorter screws solve this problem.

SWITCH




You "sock it to me" guys are knocking out your AN/ARC-54 radio's transmission with a rabbit punch to the transmission switch.

Transmission smacks your PA (power amplifier) tube with 500 volts of power. The instant voltage of a quick blow to the switch kayoes your PA tube and leaves you out when it comes to transmitting.

A count of 3 will work wonders for your radio and its PA tube. Let your set warm up for 3 minutes before you hit it with everything you've got.



WARM UP YOUR PA TUBE





LOOKS OK HERE. DON'T STOP PUSHIN'. WE SCREW SOMETHING UP, WE DO IT IN A BIG WAY.

If your R-844A/ARN-58 receiver is conking out mysteriously, eyeball the screws holding the nameplate to the CW-510 cover.

Some screws may be so long they're making contact with the B+ line when the access door is closed and shorting out the receiver.

Replace all too-long %th-in screws with 4-in ones (FSN 5305-718-9459).





All around the APH-5,

The pilot threads his cable.

The pilot makes a sudden move—POP, goes the cable.

When you plug your CX-4434/U microphone cable into your APH-5 helmet and it pops out, that's "pop goes the cable."

The 7%-in cord assembly on the MK-896/AIC is too short to give the mobility needed in some aircraft. So-o-o-o, the cable pops. out.

FSN 5995-890-8614 will get you a new cable assembly 16¼ inches long. It may seem too long for your aircraft but that's no problem. The extra length will not hamper the mike's efficiency.






XMTR

TEST

METER





Cold, thick oil moves slightly faster'n a turtle in black-strap molasses.

And it takes a heap of extra POW!-and smarts-to get it lubing all the crannies of a recip engine on a cold b-r-r morning.

'Course, when the outside air temperature is 0°C or below. Siouxmechs change the summertime oil in their OH-13's to the thinner MIL-L-22851 Type III as spelled out in TB 55-9150-200-25 (Sep 67). Thin oil lubes those dry parts sooner ... to help prevent engine failure.

SAY, THIS LIGHTER!

An ol' pro Sioux pilot knows that every 0-435-25 engine starts differently. His biggest cold-weather starting problem is spark plug "frost over"-partial fuel burning in the cylinders, or when the engine backfires and does not continue to run. In either case, it's a spark plug short-out.

He compensates for this with a richer fuel/air mixture by priming the cylinders the maximum, before pressing the starter button.

STARTING TIPS

During your preflight make sure the servos are free of ice and water.

Check carb heat and mixture controls for freedom of movement.







Release the starter as soon as the engine fires. This is real important, whirlywheelers, because the initial firing is done by the right magneto. The "coming in" speed of the left mag occurs at about 200 RPM after you release the starter button. So get your finger off the button as soon as the engine fires. This will get both magnetos firing smoothly.



If the engine doesn't start, repeat the Prime the engine with the throttle 6 priming bit and try again.

> Use restraint when priming the engine continously. You could damage the starter, flood engine, or wash lube off cylinder walls. Take a look at para 3-27c change 1 (Jul 70), TM 55-1520-224-10.

> Try these cold-weather tips, hot pilots, in addition to those in the Dash 10, and you'll have no trouble meeting minimums in the wintertime.



Never try to start the Sioux with a bat-

tery in freezing weather. Use an APU.

times.

COLD WEATHER HAS ITS PROBLEMS.

SO HERE'S A FEW PRE-FLIGHT TIPS ON

GETTING THAT SNOW BIRD AIRBORNE



A ROSE BY ANY OTHER NAME WILL SMELL THE SAME

Different bird parts with the same name can be downright confusing.

Like-maybe your favorite throttle jockey says he wants the engine inlet air filters off his Huey (UH-1) because flying conditions are ripe for the formation of ice. Iced-over filters will choke off some of the air supply.

Chap 10 of the operator's pub gives you knucklebusters the green light.


Now it so happens an upper and lower air filter is part of the particle separator located at the engine inlet.

'Taint the ones to remove. Leave 'em be!

Instead, take off the engine top air inlet filter assembly at the cowling on D/H models.

On the B and C/M models remove the top screen assembly. That'll keep the air flowing!







Medium and low pressure hose parts kits, FSN 1560-999-4645, and high pressure hose kits, FSN 1560-133-8232, are one-time issue to some Chinook (CH-47) companies. When you get 'em, tho, it's up to you supply types to request used up kit components so hoses for The Hook can be made locally. AVSCOM Supply Letter

KEEP KIT CURRENT

28-71 (May 71) lists the components.

coming unglued-an eagle eve looksee and shimmy every day. right? Outstanding! Any damage or loosey-goosey

You give your Hueybird's tail

rotor drive shaft-and all the

hardware, that keeps it from

20-MINUTE PM PAYOFF

TWICE.

IT'LL PAY OFF

movement in the flexible coupling's hanger bearing gets a quick doublecheck.

Look for a half-greased coupling job or for a half-seated seal in the female coupling groove.


A flex coupling saddled with either of these goofs means a Huey with a burned tail-tail rotor drive shaft bearing, that is ... soon!


It's easy to tell if there's no grease in the bearing. You'll get a clickity-clickcoupling slack-noise when you give the drive shaft a couple of twists on the Daily.


A smacky mouth sound means grease in the coupling.

A 20-min inspection of each coupling before you install it, or when you pull the acceptance check on an overhauled bird, makes good sense.

You'll find all the how-to PM goodies in Chap 7 of the Dash 20 manuals, birdmechs. Have a go at it!









Just use the new DA Form 3703-R (1 Mar 71), product quality inspection summary, if your unit is the first one to accept a bird from the manufacturer, contractor or depot.

Four copies of the form and 2 selfaddressed envelopes come with the bird paperwork. One envelope is addressed to USAAVSCOM and the other to the government inspection agency at the factory or depot. Send 'em each one copy.

TB 55-1500-301-25 (24 Feb 70) on the preventive maintenance inspection system says the acceptance inspection is made in enough detail to determine fitness for flight, completeness of equipment and completeness and accuracy of forms and records.

'Course, an acceptance inspection is also pulled on birds assigned from one unit to another. Use a DA Form 2404 ... no new form needed.

| 1 | | | | EQU | IPMENT | INSPECTION | AND (TM 38- | | E WORKSHEET | | |
|----|-------|------------------|------------|-------------------|-----------|-------------|----------------|-----------------------|----------------------------|---------------|------------------------------|
| ı | 1. OR | GANIZ | | | | 410 (41) | 2 | NOMENCLATURE A | ND MODEL | 7. 8 - | |
| lt | | GISTRA | TION/SERIA | | 4a. MILES | | c. ROUNDS | OH-58A d. HOT STARTS | 5. DATE 21 JUNE 7/ | 6. TYPE INSPE | TANCE |
| İ | 7. | | | | | | LICABLE R | | | Townson . | |
| | TM NU | | 1520- | 228-20 | | OCT 70 | | 55-1520 | -228-35 | OC7 | 70 |
| 7 | | 55 | 9 60 | OSSETT ORDON T | 7/1 | 86. TIME | | GNATURE (Maintena | nce Supervisor) I Johnson | 96. TIME | 10. MANHOURS REQUIRED |
| | In | TM TEM NO. | STATUS 6 | | TIS. | SHORTCOMING | s | | CORRECTIVE ACTION | | INITIAL WHEN CORRECTED |
| | | 1. | / | PILOTS H | HIN | ID INOF | , | 14 1 | | | - ' |
| | 3 | 2. | / | OIL LINE | | | | | The state of the state of | | |
| | L | * | 17 | TO DECK | 119 | | -1 | a Republica | Spirit Sprant | | 100 |
| | | 3. | / | FWD TH | R DRIV | E SHAF | 7 | 4-134-2 | en enoughery | | 18 10 17 |
| | L | | | FWD ZE | | | | Primark a | I CARRY AS UN | ord Spekins | 1 511-10 |
| | | | | SHEET M | ETAL | WORK | | and the second | And brook to | Luciel (2 | A COLUMN |
| D | A | FORM JAN 6 | 240 | 4 | | | | | | th sein | |



No sweat in filling out the 3703-R on missing or inoperable and the like. A new or overhauled birds. Section A is copy of the 2404 work sheet is acceptable done by the losing organization. The for block 13 when the entries on both gaining unit fills out Section B.

The number of safety of flight defects in block 11 are those that take a Red X. part numbers and location, to clearly Block 13 is the place to list the detail identify the problem. goofs-lock wire missing, equipment

forms are the same.

Be brief but give enough info, such as

| | ITY INSPECTION SUMMARY 55-1500-325-25; the proponent agency is lateriel Command. | Exempt from Reports Control - Pers 7-2e, AR 335-15 | |
|--|--|---|------|
| ee instructions on reverse for completing fo | | | |
| | CTION A - MAINTENANCE/PRODUCTION FACILITY | | |
| Observ. Helicopter (OH-58A) S/N 71862 | Bell Hel. Co. | 3. TYPE WORK X NEW OVERHAUL MOD REPAIR OTHER (Specify) | - |
| . CONTRACT/DMWR NUMBER | 5. GOVERNMENT INSPECTION AGENCY | 6. DATE ACCEPTED | 6 |
| A4172318-315 | SAVBE (AVSCOM) | 21 June 71 | 7 |
| | SECTION B - RECEIVING INSPECTION ACTIVITY | | - |
| INSPECTING ORGANIZATION | 8. ORGANIZATION CODE | 9. DATE RECEIVED INSPECTED | 13/1 |
| O. CONDITION | 11. NUMBER DEFECTS | 12. ESTIMATED MAN-HOURS TO | - |
| SATISFACTORY UNSATISFACTORY | SAFETY FLIGHT OTHER | REPAIR | 1 |
| 3. ITEMIZE SAFETY OF FLIGHT DISCRE | PANCIES/RECOMMENDATIONS | | AL |
| ORM 3703 - R, 1 Mar 71 | | YOU FILL OUT THIS | Á |


This feedback info will help cut down on the amount of extra maintenance a unit needs to do, following acceptance inspections. The details are spelled out in TB 55-1500-325-25 (11 Mar 71).



Any excessive vertical vibration in the Hook's (CH-47) rotor blades may call for a blade tracking job—adjustment of the pitch links.

If you use a wrench to hold the upper red end flat while you loosen the lower checknut, you'll get a couple of busted link assembly rivets, a ding-a-ling bird, beaucoup downtime.

By-the-book preventive maintenance practices—in para 9-266a(6) of TM 55-1520-227-20-2 (Aug 70) saves \$366 in bread... the price tag on link assemblies.



When you break the 800-1,100 in-lb torque on the lower checknut of the link assembly, keep the rod end from turning by using a wrench on the lower rod end flat.

You have to loosen the 2 checknuts on the pitch change link to adjust the turnbuckle.



NEWER BRACKET

I KNOW I SHOULD HAVE PUT "NO SUBSTITUTE" ON THAT REQUISITION!



If you Cobra hotshots are totin' the XM-35 20-MM weapons subsystem, focus in on the magnetic compass.

Vibration can crack the mount, so now there is a beefed up job, FSN 1560-181-5129, in the supply system.

Put "No Substitute" on the requisition to make sure you get the new bracket.

Your favorite 67Y birdmech can make the mount switch for you.






The trouble with hydraulic filler and bleeder, Fed Cat Class 4910, in your A Sup, B and C tool sets is that it is primarily designed for non-aircraft use. The rubber seals in it work just fine with non-mineral base hydraulic brake fluid.

Mineral base hydraulic fluid, MIL-H-5606, is used in bird hydraulic systems.

So, when the bleeder gets filled with mineral base red juice the seals go to pot.

The unit leaks like a sieve and rubber



You want—Dispenser, Hydraulic Fluid, FSN 4920-245-1832. It uses MIL-H-5606 and you'll find it now listed in SC 4920-99-CL-A71 (May 71). Condemn the old bleeder because the seals are shot.



NEW ELEMENT-OLD STORY

One way to sideline a bird is to run out of parts before you should. And that's just what's happening with the hydraulic flight control filter on your Huey (C model not affected).


MWO 55-1500-206-20/1, with Ch 1 (Sep 69) put in an improved filter with a new filter element. Serial-numbered birds to be modified are listed in the MWO. All others have the filter.

Now, it just so happens, the new element, FSN 4330-442-2484, has a metal core and gets changed every 10th Periodic inspection. 'Course the supply of that baby is based on it going the distance.

The old filter has a paper element, FSN 4330-542-2060. It has a spring core and gets changed every Periodic.

The problem? You guessed it!

Some knucklebusters are replacing the metal element every Periodic—9 times more often than it should be changed. 'Course you wouldn't fall into that trap, right? Not when the element change frequency is spelled out right on the checksheets.



PAPER



Dear Windy,

Change 2, TM 55-1500-204-25/1 (Apr 70) says all safety wiring and cotter pinning will be done according to Military Standard MS 33540.

Outstanding! But how do we get a Military Standard or Specification?
Where do we get 'em and can we get our hands on a catalog which lists 'em?
CS3 D.M.H.

Dear Mr. D. M. H.,


Quite a number of Army technical publications and regulations used in the field refer you to various Mil Specs and Mil Standards. So, you've gotta get 'em.

You need DOD Index to Specifications and Standards, Part I (alphabetical listing)

and Part II (numerical).

You can start automatic distribution of the index with a letter to: Commanding Officer, U.S. Naval Supply Depot, 5801 Tabor Ave., Philadelphia, PA 19120.

If you need a specific Mil Spec or Mil Standard write to the same address, ATTN: Customer Assistance. Use DD Form 1425—in duplicate.



DUMP IT!

A LETTER GETS YOU THIS INDEX



Dear Specialist J. B. B.,

No sweat!

The Army Aviations Systems Command has approved an engineering change that no longer requires the cable on either U-21 or U-8 aircraft.

These cables can come loose and cause FOD—a more clear and present danger than any possible damage caused by static buildup.

When the wire wears out just dump the holder, nut and cable.





LOST


A 67N whirleymec was missing a pair of small slip joint, angle nose pliers from his general mechanics tool box.

FOUND

An Armymech found the pliers lodged on the Huey Delta's cyclic stick lateral control tube ... after a 3-stop, 450-mile trip!

Peter Pilot could have been without directional control or communications if the pliers had jammed the lateral cyclic control bellcrank or shorted a bundle of wires. He was lucky.





readiness bind.

You're not authorized

to order extras when

vou use an A UND on a supply request. which are at zero bal-

ance.

22. SERIAL/LOT NUMBER

From the UND you select, read across to your assigned FAD. When you line-up your FAD with your UND you pinpoint your PD.

61



On A DA Form 2765 you note the PD in block 20. On DA Form 2402 you put the IPD in block 4, after the FSN. (Your UND is not recorded on either supply form.) On DA Form 2407, the code goes in the PD block in Sect I.

Have your CO sign DA Forms 2402 and 2407 when a high priority PD is used.



On supply requests, when you use PD's 01 through 08, you need your CO's signature (or, in his absence, the signature of whoever's authorized to sign for him) in block d of your document register, DA Form 2064. The other PD's don't take a signature, but you must note 'em in block a (ahead of the date) on your document register.


| | | | ORGANIZATION/ACTIVITY | UNIT IDENTIF | UNIT IDENTIFICATION | | DATES (Day, Month, Year) | | | |
|---|------------------------|----------------|-------------------------|--------------|---------------------|------------|--------------------------|---------------|-----------------|------|
| DOCUMENT REGISTER FOR SUPPLY ACTIONS (AR 735-35) | | TIONS | CODE | | ARX39 | | 1176 | | y, Month, Year) | |
| DA 2064 | DOCUMENT SERIAL NO. | CONTROL NUMBER | REMARKS | | SUP SPT ACTIVITY | QTY REQ | REC OR TURNED IN | QTY DUE-IN | DATE | MISC |
| 06/1176 | 0001 | THURST | 3110-100-0684 CONE & RC | PILLER | 193 | 2 | 2 | | 1179 | 633 |


EXCEPTIONS ALL UNITS, REGARDLESS OF FAD.

USE THESE PD'S

PD 03 when there's an emergency for medical and disaster supplies, and for equipment and supplies needed immediately to save lives and prevent suffering, quell iots, etc.

PD 06 on emergency requests for individual and organizational clothing needed to provide minimum essential items for active duty personnel. The troops must actually be minus the requested items.





NORS CODES ON SOME NORS* REQUESTS, WITH PDS OF 01, 02 OR 03, YOU USE COPE 999 The 999 code, however, is OK'd only

when you're overseas, or when you're

stateside and alerted for deployment

within 30 days. And you use the code on

requests for supplies related to critical

equipment ... limping equipment that'll

fracture your unit's equipment readiness

It's also for supplies needed for pending repair or replacement work on critical equipment that's tagged ANORS (Anti-

cipated Not Operationally Ready Sup-

ply). That means items that'll be needed

within 15 days of the date of the request

if you're in VN, and within 5 days of the


date of the request if you're elsewhere,

overseas, or stateside and alerted for

deployment within 30 days. These are

THIS SPECIAL HANDLING CODE GOES IN BLOCK 21 ON DA FORM 2765.

*NOT **OPERATIONALLY** READY SUPPLY



nance, inspection, or testing experience) as definite time-change items to prevent failure of primary weapons or other equipment.

Your CO, or whoever signs for him. OK's use of the 999 code.




Also, on stateside NORS requests (when you're not alerted for deployment) slip an N in the first position in block 21, and on an ANORS requests use an E in that space.

For the list of weapon system codes for equipment that rates NORS requests see the Army System codes in App IIitems that've been identified (by mainte- 15, pages A2-108-A2-110, AR 725-50.

FOR MORE SCOOP ...

The streamlined UND/PD codes were effective on 1 July 1971, and were put into effect by DA Letter, LOG-SP-PPB (5 May 71), Subj: Uniform Materiel Movement and Issue Priority System (UMMIPS).





interest to organizational maintenance personnel. This list is compiled from recent AG Distribution Centers Bulletins. For complete details see DA Pam 310-4 (Jun 71), and Ch 1 (Aug 71), TM's, TB's, etc.: DA Pam 310-6 (Jul 71), SC's and SM's; DA Pam 310-7 (Aug 71), MWO's; and DA Pam 310-9 (Jul 70), COMSEC

TECHNICAL BULLETINS

TM 5-3895-340-20P Sep Roller, Motorized 5-8 Ton GED Bituminous TM 5-4110-228-24P Aug Refrig Unit TM 5-4320-258-12 Aug Pump POL GED 1120 GPM TM 5-551B Jul Carpenter TM 5-6665-203-20P Aug Land Mine Detection Bridge type truck mounted TM 9-1005-211-21 C3 Oct M1911A1 45 Pieto TM 9-1005-257-12 C3 Sep 7.62MM MG Armament POD XM18/XM18E1 TM 9-1005-257-20P C2 Sep 7.62MM MG Armament POD XM18/XM18E1 TM 9-1005-298-12 C2 Sep 7.62MM MG Armament Subsystem XM27E1 TM 9-1015-234-12 C6 Aug M102 TM 9-1090-202-12 C2 Sep 7.62M MG 2.75 Inch Rocket Launcher Armament Subsys M21 TM 9-1090-203-12 C3 Aug Armament Subsys XM28/XM28E1 TM 9-1090-203-12 C4 Sep 7.62MM MG 40MM Grenade Launcher Armament Subsys XM28E/XM28E1 TM 9-1400-514-15 C4 Oct Hawk TM 9-1410-500-15P C1 Jul Hawk TM 9-1425-585-14 C3 Jul Organizational Chaparral TM 9-1430-510-12/1 C7 Sep Hawk TM 9-2320-211-ESC Aug TM 211series 5-ton trucks TM 9-2320-218-20P C3 Aug TM-218series 1/4-ton trucks TM 9-2330-251-14 C1 Sep TM-251-Series 1/4-ton trailers TM 9-2350-300-20/2 Aug Vulcan Self-Propelled XM163 TM 9-6625-2536-14 Aug TOW Differential Multimeter 6625-489-8908 (TOW Hvy Antitank/Assault Weapon TM 10-3950-203-20 Aug Crane Truck

Warehouse Slewing Boom; GED; 10,000

TM 11-5410-205-15P Sep Shelters, Electrical Equip S-144/G, S-144A/G, S-144B/G, S-144C/G and S-144D/G TM 11-5820-556-15 Jul Radio Terminal Set AN/TRC-112 TM 11-5820-667-12 C3 Sep AN/PRC-77 Radio Set TM 11-5821-248-12 C2 Sep OV-1A. B, C, U-1A, U-6A, U-8F, U-10A, CH-47A, UH-1B, D TM 11-5841-241-12 C3 Sep U-21 TM 11-5895-479-12 Aug Interrogator Set AN/TPX-41 TM 55-406 C1 Aug All Fixed & Rotor Wing TB 55-1500-219-20/2 Nov UH-1B, D, H TM 55-1500-323-25 C3 Sep All Fixed & Rotor Wing TM 55-1510-203-10 C3 Sep U-6 TM 55-1510-204-10/4 C4 Oc OV-1A, B, C TM 55-1510-204-10/5 C7 Oct OV-1D TM 55-1510-204-20-1 C13 Au OV-1A, B, C TM 55-1510-205-10 C2 Sep U-1 TM 55-1520-206-PMD Aug OH-23 TM 55-1520-206-10 C1 Sep OH-23 TM 55-1510-209-CL/4 Jul U-21 TM 55-1510-209-10/1 C2 Oct U-21 TM 55-1520-209-20P-1 Aug CH-47A, TM 55-1520-210-10 Aug UH-1D, H TM 55-1520-214-20 C10 Oct OH-6 TM 55-1520-217-CL/1 C1 Jul CH-54A TM 55-1520-219-20 C10 Oct UH-1B TM 55-1520-219-20 C8 Sep UH-1B TM 55-1520-219-20 C9 Sep UH-1B TM 55-1520-220-20 C17 Sep UH-1C TM 55-1520-220-20 C18 Oct UH-1C TM 55-1520-221-20P C1 Sep AH-1G TM 55-1520-226-10 C6 Sep OH-13T TM 55-1520-227-10 C9 Oct CH-47B, C TM 55-1520-227-20-1 C16 Au CH-47B. C TM 55-1520-228-10 C6 Oct OH-58 TM 55-1520-228-20 C4 Aug OH-58 TM 55-1520-228-20P Aug OH-58

TM 55-1730-215-13 Jul A11 Fixed & TM 55-2810-222-20P C1 Sep OH-23 TM 55-2840-230-20P Aug CH-54A, B TM 55-2840-230-24 Sep CH-54A, B TM 55-2840-231-20P Aug OH-6 & TM 55-2840-234-24/1 Aug CH-47A, B, C Engine, Shaft Turbine TM 55-6230-239-15 C1 Aug All Fixed & Rotor Wing

LUBRICATION ORDERS

LO 5-3810-290-12-1 Jun Crane Wheel LO 5-3810-294-12-1 Sep Crane, Truck Mounted, 20 Ton LO 5-3810-294-12-2 Sep Crane Truck Mtd 20-Ton LO 5-3810-294-12-3 Sep Crane Truck Mounted 20-Ton LO 5-3810-294-12-4 Sep Crane Truck LO 5-3810-294-12-5 Sep Crane Truck Mtd 20-Ton LO 5-4320-258-12 Jul Pump, POL, GED 1120 GPM. Operator Petroleum LO 9-1430-254-20 Aug Imp Nike-Herc

MISCELLANEOUS

AR 220-1 Sep Unit Readiness

DA Pam 310-7 Aug MWO's FM 29-2 Aug Organizational Maint Mgt MWO 55-1510-201-40/17 C2 Oct U-8 MWO 55-1510-209-40/3 C1 Oct U-21 MWO 55-1500-219-30/2 C1 Sep TB 10-1670-205-20/2 Oct Inspection of Waistband Adapter Panel On Harness, Personnel Parachute TB 750-971-3 Jul EIR and Maint Digest (MECOM) TB 750-981-3 Jul EIR and Maint Digest Tank and Automotive Equip

Mwo Of The Month

CONNIE! Connie's I'VE GOTTA MAINTENANCE PROBLEM Mini Mini's 0 Letters Up Front Battery Dates

Some new-style USA registration numnew equipment. Instead of digits up front, as now, they'll have 2 letters up front. Change 1 (Aug 71) to AR 708-1 spells out the word on it. Old-style numbers now on equipment won't change—unless HQ USAMC gives the word.

A /C Inventory Form

Ask your pubs people to latch onto the new DA Form 1352 (1 Jul 71) for your aircraft inventory, status and flying time reports, birdmen. That's the baby you need to comply with AR 710-12 (Jul 71).

Battery maintenance policy is one bers will soon start showing up on thing—battery ESC ratings are something else. Even though vehicle ESC ratings no longer require a check on battery dates, the battery TM (TM 9-6140-200-14 (Aug 71), para 3-7, requires a service date to be stamped or marked near the battery positive post. That's for general battery maintenance management—not for ESC

Door Stop Repair

Busted door-stop brackets on your 2½-ton truck can be fixed. See the repair rundown in Article 3-10. TB 750-981-2 (Apr 71).

Stop Freeze-Up

When temperatures drop, water-logged fuel will freeze your equipment to a standstill.

Whether you operate a gasoline, multi-fuel or diesel engine, be safe by mixing 1/2 pint of denatured alcohol (FSN 6810-543-7415) to every 10 gallons of fuel.

And be extra safe by only using fuel that has been pumped through a filter/separator.

Drain your primary fuel filter after every daily operation and the fuel tank sediment weekly if possible.

Keep your bulk fuel and dispensing equipment free of ice and snow.

Keep fuel tanks full to cut down condensation.

And follow the dope given in TM 9-207 (Dec 70) to the letter.

Would You Stake Your Life Mon the Condition of Your Equipment?

